25X1

25X1

25X1

TOP SECRET

APR 18 AM 11: 22 2628 JUJIATE KAØ13/18 OO YFEAB DE YFAGNXF Ø2M EXCLUSIVE FOR CLA, WATCH OFFICER TOPSECRE 0 18Ø44ØZ FM AFSSO HQ 15TH AIR FORCE TO AFSSO HQ USAF CITE: GTS 251-58. TOP SECRET THIS IS AN A SUMCMARY OF RUDIMENTARY ANALYSIS ON ELINT TAPE COVERING MISSION ONE SEVEN THRE ZERO FLOWN 17 APRIL 35 FOLLOWS: SYSTEM Ø - B - S TONE LEFT SIDE OKGM TON RIGHT SIDE GAV OKGM BUZZER LEFT AND RIGHT SID AV OK. STARTEM (CW TONE CHANGING FEQ ON RIGHT IDE. PRESENT THRU
TONE AND BUZZER CHECKS.) 40000° ØØØ4 MEDIUM PRF RIGHT SIDE, 15.6 SEC S/R. HIGH PRF RIGHT SIDE, 3.R SEC S/R. 0004 1/2 MEDIUM PRF LEFT SIDE, TOO WEAK TO ANALYZE.
0007 MDIUM PRF LEFT IDE, 17.1 SEC S/R.
0008 HIGH PRF RIGHT SIDE, STRONG NOW, 3.6 SEC S/R.
0011 NO SIGNALS RIGHT SIDE. (CON - - -H/W RPTNG - - -HIGH PRF RIGHT SIDE, STRONG NOW, 3.6 SEC S/R.
NO SIGNALS RIGHT SIDE. (CONTINUOUS VOICE PRESENT PLUS
QUITE A BIT OF AMPLIFIER NOISE) 0008 90011 MEDIUM PRF LEFT SIDE ONLY. SIGNAL AUDIBLE.
ANOTHER MEDUM PRF LEFT SIDE, 10.4 SEC S/R. RECORDING NOISY.
(IKC TONE STILL NOT AUDIBLE) ØØ12 0013 MEDIUM PRF LEFT SIDE 17.1 SEC S/R IS NO LONGR AUDIBLE.
IGNAL LEFT SIDE 10.4 SEC S/R, STRONG NOW, (8\$3)9?3-7\$8?)3.
SIGNAL LEFT SIDE FADING NOW. 0014 ØØ19 ØØ25 NO SIGNALS AUDIBLE. ØØ3Ø 0034 1/2 ONE ILLUM OF LOW PRF LEFT SIDE.
0044 CHATTERING MEDIUM PRF RIGHT SIDE, ONE ILLUM HEARD.
0045 SIGNAL HAS S/R OF 19.1 SEC. (IKC TONE STILL NOT AUDIBLE). ØØ47 SIGNAL FADING. MEDIUM PRF RIGHT SIDE 9.1 EC S/R. CHATTERING SINGAL BECOMING STRONGER. (IKC TONE STILL NOT AADIBLE). BOTH SIGNALS RIGHT SIDE STILL PRESENT. 0054 Ø1ØØ BOTH SIGNALS FADING IN AND OUT NOW. Ø1Ø5 Ø112 NO SIGNALS PRESENT. NO SIGNALS PRESENT. (IKC TONE NOT AUDIBLE). Ø13Ø NO SIGNALS PRESENT.
NO SIGNALS PRESENT. (ASSUME IKC TONE NOT RECORDED).
NO SIGNALS PRESENT. Ø145 Ø2ØØ Ø**21**5 Ø23Ø NO SIGNALS PRESENT. NO SIGNALS PRESENT. Ø245 NO SIGNALS PRESENT Ø3ØØ END REEL NUMBER ONE. TART REEL NUMBER TWO. NO SIGNALS PRESENT. Ø31Ø Ø315 NO SIGNALS PRESENT. NO SIGNALS PRESENT. Ø33Ø 0334 1/2 MEDIUM PRF RIGHT SIDE. ONE ILLUM HEARD. NO SIGNALS PRESENT.
NO SIGNALS PRESENT. Ø345 Ø4ØØ NO SIGNALS PRESENT. Ø415 NO SIGNALS PRESENT. Ø43Ø NO SIGNALS PRESENT. Ø445 Ø5ØØ NO SIGNALS PRESENT. NO SIGNALS PRESENT. NO SIGNALS PRESENT. NO SIGNALS PRESENT. Ø515 Ø53Ø 0545 0545 1/2 MEDIUM PRF RIGHT SIDE, WEAK, UNABLE TO BOTAIN S/R. 0549 SIGNAL HAS 10.3 YDCIS/R. SIGNAL DOWN. Ø552 Ø555 MEDIUM PRF LEFT SIDE 5.7 SEC S/R. Ø559 SIGNAL DOWN. NO SIGNALS AUDIBLE.
NO SIGNALS AUDIBLE. Ø6ØØ ØS 15

MEDIUM PRF RIGHT SIDE, TWOO WEAK TO BOTAIN S.RGM

EN 0625 ENDRUL
Approved For Release 2007/10/19: CIA-RDP78T05447A000400010034-4

0619

GREEP

```
ZAII
                   Approved For Release 2007/10/19: CIA-RDP78T05447A000400010034-4
5665
                 NO SIGNALS AUDIBLE.
                   MEDIUM PRF RIGHT SIDE, TWOO WEAK TO BOTAIN S.RGM
END REEL NUMBER TWO. START REEL NUMBER THREE.
ONE SWEEP OF SIGNAL TIMED AT 11.5 SEC. BELIEVE S/R TO BE HALF
Ø619
GPYWP
ØS 25
                    THAT AMOUNT.
Ø53Ø
                   SIGNAL STILL PRESENT, S/R REMAINS THE SAME.
Ø635
                   SIGNAL DOWN.
          MEDIUM PRF LEFT SIDE, POSSIBLE SAME AS AT 3625.
SIGNAL NOW RIGHT SIDE.
SIGNAL NOW LEFT IDE.

1.2 SIGNAL NOW RIGHT SIDE A S/R STILL 11.5 SEC.
3643
3542
Ø643
9645
20.55 SIGNAL STRONGER NOW. MEIUM PRF LEFT SIDE 5.8 SEC S/R. SIGNAL RIGHT SIDE HAS 5.8 SEC S/R ALSO.

20.55 HI PRF RIGHT SIDE, TOO WEAC TO ANALYZE. AMOTHER MEDIUM PRF
20.570 LEFT SIDE 9.7 SEC S/R.

20.570 NO SIGNALS NOW RIGHT SIDE. FADED FAST. SIGNAL LEFT SIDE FADING.
3655
Ø$57
3793
9792 1/2 MEDIUM PRF RIGHT SIDE 5.6 SEC S/R.
                  SIGNAL NOU LEFT SIDE. MEDIUM PRF HEARD LEFT SIDEGN QUMR SEC S/R.;?3)83;3 /R IN ERROR. bleeve / menon;;32,-) 4325 383;-$8,2. bleeve / menon;signal LEFT SIDE DOWN.

SIGNAL RIGHT SIDE DOWN.
Ø7 Ø3
37 Ø4
&Ø7Ø6
Ø7 Ø9
715 NO SIGNALS PRESENT.

9717 1/2 MEDIUM PRF LEFT SIDE, WEAK, TWO ILLUMS HEARD.

9719 SIGNAL HEARD AGAIN, NOT HEARING EVERY ILLUM.
Ø72Ø
                   S/R 11.3 SEC.
                   SIGNAL BECOMING STRONGER, S/R STILL 11.3 SEC.
Ø722
                   SIGNAL FADING IN AND CUT.
SIGNAL DOWN.
NO SIGNALS PRESENT.
NO SIGNALS PRESENT.
Ø725
Ø732
2745
                                                                  no seguels present
9892
                 ;,98&,-) -7
NO IGNALS PRESENT.
Ø815.
                   CHATTERING MEDIUM PRF LEFT SIDE, 19.1 53: /R.

AMOTHER MEDIUM PRF LEFT SIDE, VERY VEAK.

SECOND SIGNAL LEFT SIDE HAS S/R OF 9.7 SEC.

BOTH SIGNALS FADING IN AND AOUT.

MEDIUM PRF 9.7 SEC S/R DOUN. CHATTERING SIGNAL STILL PRSENT.

CHATTERING SIGNAL VERY VEAK.

;32,-)-)534,-53)6 2VVEAK AND STRONG. Signal alternotally weak

CHATTERING SIGNAL DOWN.

MEDIUM PRF RIGHT SIDE, VEAK, 20.1 SEC S/R.

END REEL NUMBER THREE.
ØSØ
Ø839
Ø847
0849
Ø85Ø
Ø9 Ø3
Ø9 Ø9
Ø9 1 1
9919
Ø933
0934
51 Ø Ø
18/0655Z APR
```

MNNM

TOP SECRET

OP IMMEDIATE

25**X**1